

The  
**Ostrich**  
The Industrial Inspection  
Polecam System  
from  
[www.polecam.com](http://www.polecam.com)



## Content list and quick start guide

---



- 6 or 10m telescopic pole, packed in the soft bag
- Hard case with foam insert
- Tilt unit with camera and torch
- Control knob unit with clamp
- Control curly cable (1pc with 6m or 2 pcs with 10m pole)
- SD card (inside the camera)
- Spare camera battery
- Spare torch battery
- Torch charger and accessories
- Camera USB Cable

1. Attach the Tilt Unit to the pole and lock quick release plate.



2. Make sure, that safety wire is attached to the Tilt Unit.




3. Mount the Control Knob Unit and smartphone mount, on the pole.



4. Connect the Control Knob with Tilt Head, using the curly cable.



5. Download the PIXPRO Remote Viewer app and connect the camera with your smartphone via Bluetooth



6. When Ostrich is ready to use ,adjust the tilt, turning the control knob. Step on the foot latch while using the Ostrich for better stability.





# The **Ostrich**

[www.polecam.com](http://www.polecam.com)  
4b Kenneth Way, Wilstead Industrial Park,  
Bedford, England, MK45 3PD  
Telephone: +44(0) 1234 855 222